



If condensers are connected in parallel, allowance must be made for the fall in pressure in the condensers on the refrigerant side. If necessary, fall lines must be applied.

