







SLAVE MODULE WIRING DIAGRAM



LD01940

FIG. 19 – SLAVE MODULE SYSTEM WIRING (Cont'd)