

Fig.1

When repairing only the pilot valves, the service kit for EVM (NC) and EVM (NO) can be used.

Service kit EVM (NC) code no. 032F1116
 Service kit EVM (NO) code no. 032F1117




Fig.2

Description	Type	Size 80 (3in.)	Size 100 (4 in.)	Size 125 (5 in.)	Size 150 (6 in.)
		Code no.	Code no.	Code no.	Code no.
Spare part kit, for top/housing and cap (Dismounting set) Pos. 17 Gasket top/housing Pos. 36 O-ring for cap	all	148G3427	148G3428	148G3429	148G3430
Repair kit, complete set of gaskets Pos. 17 Gasket top/housing 18 Teflon ring cone step 2 19 Teflon ring cone step 1 25 O-ring piston inside 26 O-ring piston outside 27 Glide ring piston outside 28 O-ring guide 29 Glide ring guide 30 Glide ring piston inside 34 O-ring for connection part/ solenoid valve 35 O-ring for threaded rod 36 O-ring for cap 39 Gasket for cylinder top 40 gasket for cylinder	all	148G3431	148G3432	148G3433	148G3434
New Additional Repair kit Pos. 4 Piston rod 15 Spring open		148G0100	148G0101	148G0102	148G0103
New Overhaul kit Pos. 5 Cylinder 6 Piston 7 Guide piece 23 Screw 43 Screw		148G0104	148G0105	148G0106	148G0107
Complete pilot valve block type EVRB without coils Pos. 31 EVRB valve block 32 Bolts for solenoid valve 34 O-ring for connection part / solenoid valve	all	2453+103	2453+103	2453+103	2453+103
External/pilot connection complete, fig.2	all	148G3750	148G3750	148G3750	148G3750