



Results of Investigation



Internal freezing



Bad water quality




Fatigue & Overload



Water hammer



Copper corrosion



316 corrosion

- Internal freezing
- Bad water quality
- Fatigue and overload
- Water hammer
- Copper corrosion
- 316 corrosion
- Wrongly assembled
- Freight damage